

Installation Of Electrical Switches



Site:

73 Lancaster Close

Client

Lana Duncan

Prepared by:
John King
02075462589

Handwritten signature of John King

Signature.....




Asset: Socket
Assigned to: Bobby Bolt
Condition: Damaged

Location: Master Bedroom
Status: OPEN
Category: OBS

Damaged electrical socket needs replacing


Date Created: 23-09-2020

Due Date: 30-09-2020



fuse box has been reset





Assigned to: Bobby Bolt

Category: OBS

Fuse Box Needs To Be Inspected

Date Created: 23-09-2020

Due Date: 30-09-2020

